

Firmware revision history

Revision	Date	Changes
2.16.2	12/03/24	Fix- Added a delay in the SWLS settings, to prevent interruptions to the driver when it saves to its memory. Remark- Do not turn off the system until the SWLS commands are complete.
2.16.1	18/02/24	Improvement- Dual Gimbals- ' <i>Inner mode</i> ', Description can be found in the ' <i>Command and Control API</i> ' document. Fix- Enable general operations (such scanning, preset etc.) with each Dual Gimbals mode. Fix- Scanning- snake movement.
2.16.0	20/12/23	Improvement- Software limit switch- setting the software limit switch handler (controller/driver/both). Activate ' <i>slowdown</i> ' mechanism. Description can be found in the ' <i>Command and Control API</i> ' document. Improvement- New error register to indicate if one of the motion operations wasn't completed successfully. Description can be found in the ' <i>Command and Control API</i> ' document. Improvement- New Error position indication for absolute mode. Description can be found in the ' <i>Command and Control API</i> ' document. Improvement- Set faults in motor error register when communication with driver is lost. Improvement- Reading the number of satellites from AN GPS. Fix- motor error message.
2.15.1	12/11/23	Improvement- Dual Gimbals- ' <i>Sighting In</i> ' mechanism, Description can be found in the ' <i>Command and Control API</i> ' document.
2.15.0	9/11/23	Improvement- main operations timing. Improvement- optimization the readings from the drivers. Fix- Homing on startup (using startup register). Fix- Dual Gimbals – absolute movement with software limit switch.
2.14.3	11/10/23	Improvement- New MPU IMU integration. Fix - Dual Gimbals- software limit switch in Sync mode. Improvement- Reading absolute encoder position from the drivers.

2.14.0	6/8/23	<p>Feature- Dual gimbals Implementation. Description can be found in the '<i>Command and Control API</i>' document.</p> <p>Improvement- New Cube drivers' integration.</p> <p>Improvement- New AN GPS integration.</p> <p>Fix- 'preset' angles in a range of 0 to 360°.</p> <p>Optimization- Software limit switch- negative position must be less than the positive limit.</p> <p>Optimization- Blocking negative position commands in absolute mode.</p>
2.13.8	23/7/23	<p>Fix- Absolute movement with short path.</p> <p>Fix- Leveling operation considering the software limit switch.</p>
2.13.7	14/5/23	<p>Fix- 'Go To Target' operation for Roll & Tilt systems</p> <p>Improvement- Adding filter for IMU readings in stabilization loop. Description can be found in the '<i>Command and Control API</i>' document.</p> <p>Issue- Absolute movement with short path</p> <p>Unavailable Firmware</p>
2.13.6	27/4/23	<p>Fix- The return opcode of 'get OvdGPS' command.</p> <p>Fix- Absolute encoder readings timing.</p> <p>Feature- Offset for IMU readings. Description can be found in the '<i>Command and Control API</i>' document.</p>
2.13.5	19/3/23	<p>Fix- The calculation of Euler angles from IMU readings.</p> <p>Fix- Changing the minimum value of stabilization acceleration.</p>
2.13.4	7/12/22	<p>Fix- Opcodes of stabilization settings commands.</p>
2.13.3	29/9/22	<p>Improvement- Stabilization loop- settings of control type, max error and speed command for position control loop were added. Description can be found in the '<i>Command and Control API</i>' document.</p>
2.13.2	30/8/22	<p>Improvement- Homing function according to the absolute encoder</p> <p>Fix- Using 'General Spd' variable in Leveling operation (instead of fix speed value).</p>
2.13.0	28/8/22	<p>Feature- Bootloader implementation</p> <p>Improvement- Stabilization loop of Roll & Tilt systems</p> <p>Fix- Stop motors in Keepalive mechanism</p>

2.12.6	20/7/22	Fix- Software limit switch with reverse axis.
2.12.5	22/6/22	Improvement- Software limit switch with absolute encoder. Fix- Limiting the number of leveling attempts.
2.12.4	13/6/22	Improvement- Targets, Presets, scanning and stabilization operations for one axis systems. Improvement- Targets, Presets and scanning operation while stabilization is active.
2.12.3	24/5/22	Improvement- Stabilization loop- Roll compensation was added. Description can be found in the ' <i>Command and Control API</i> ' document. Fix- Reset VN IMU
2.12.2	31/3/22	Improvement- Motion commands while stabilization is active. Fix- Initialization position of Scanning.
2.12.1	21/3/22	Fix- Drivers communication for one axis systems.
2.12.0	15/3/22	Feature- Keep Alive mechanism. Description can be found in the ' <i>Command and Control API</i> ' document. Feature- Startup register. Description can be found in the ' <i>Command and Control API</i> ' document. Feature- Set the position range. Description can be found in the ' <i>Command and Control API</i> ' document. Feature- Leveling operation. Description can be found in the ' <i>Command and Control API</i> ' document. Improvement- Drivers communication- reading motors data. Fix- blocking movement commands while one of motion operation is active.